



Elevator Round Table Discussion



Herrity Building
Rooms 106/107
January 22, 2024
11am - 1pm

Agenda

- Entrapments and Accidents
- Change of Contact Info.
- PLUS Updates
- Goals/Expectations
- Work without Permits
- Q & A
- Next Meeting



Accident/Entrapment Policy

- When an accident/entrapment occurs, the affected equipment shall be removed from service immediately.
- Over 1000 reported in 2023
- Prior to placing back in service, all fees paid, and current certificate shall be issued.
- County/ATIS will respond within 2 hours of notification.
 - Incorrect data will delay response

Change of Contact Information

- Three Contact Options:
 - Owner Agent
 - Onsite Contact
 - Maintenance Company
- It is the responsibility of the **building owner**, or designated **responsible party**, to update this information. Failure to do so may result in **fees**.
- [Click Here...](#)

PLUS

■ Application

- Floor Plans

■ Fees

- You *MUST* be assigned to see on your account

■ Plan Review

- Average 14 days (Holidays and Staffing)
- Resubmissions Fees, Response to Corrections...delays
- Min. Submission Checklist (COMING SOON Q2)


■ Inspections

- Scheduled through Elevator Website (ATIS)



2024 Goals & Expectations

- Annual Inspections
 - All annual inspections shall be scheduled and commenced within the equipment's diary month
- Reinspection's
 - Upon a failed inspection result, the reinspection shall be scheduled and commenced within 40 days.
- Periodic Inspections
 - 90% completed in the month due.
- Removal from Service
 - Reduce the time units are OOS



Code Update-January 2024

- January 18, 2024
- Adopted 2021 Virginia Construction Code
 - 2019 ASME 17.1
- One-year grace period
 - Applicant can choose between the existing code, or the adopted code for permissible work.
- Inspections are based on the 2019 ASME 17.1 8.6
 - Inspection Standard

Questions?



“That’s all Folks!”